


Piastre di guida a saldare



Guide plates to be welded
 Plaque de guidage à souder
 Führungsplatte zum Schweißen



Cod.	A	B	C	S	R min-max	Rulli Rollers Roulements Walzen	
261	136	60	36	2,5	40-60	2 Ø 35	8
361	136	200	36	2,5	40-60	4 Ø 35	4
168	220	330	72	4	60-100	4 Ø 52	4

Piastre di guida robuste a saldare



Strong guide plates to be welded
 Plaque de guidage résistante à souder
 Feste Führungsplatte zum Schweißen



Cod.	A	B	C	S	R max	Rulli Rollers Roulements Walzen	
266	150	80	65	4	75	2 Ø 30	4
366	190	100	70	4	95	2 Ø 42	4
265	150	200	65	4	75	4 Ø 30	4
365	190	250	70	4	95	4 Ø 42	4

Staffa di guida a fissare

Guide bracket to be fixed
 Plaque de guidage à visser
 Führungsbügel zum Fixieren



Cod.	A	B	C	H	S	R max	Rulli Rollers Roulements Walzen	
257	180	50	65	90	6	100	2 Ø 30	4
258	200	80	70	175	6	100	2 Ø 42	4