

INCONTRI per SOLUZIONI ad 1 ANTA					
Scontro per RIBALTA-ANTA KD	Scrocco porta	Scontro AFM	Invito per serramento ad ARCO	Scontro MICROAERAZIONE	Cerniera centrale a scomparsa in teflon lato telaio
6-32668-00-0-1	K-17044-00-0-1	9-40067-00-0-1	6-24201-03-0-1	6-34844-00-0-1	9-40872-00-0-1
-	K-17044-00-0-1	9-40444-00-0-1	6-24201-03-0-1	6-34844-00-0-1	9-40872-20-0-1
6-35779-00-L/R-1	K-17119-00-0-1	9-42684-00-0-1	6-24201-03-0-1	6-34846-00-0-1	9-41850-00-0-1
6-35779-00-L/R-1	K-17120-00-0-1	9-42684-08-0-1	6-24201-03-0-1	6-34846-00-0-1	9-41850-08-0-1
6-32668-00-0-1	K-17068-00-0-1	9-40244-00-0-1	6-24201-03-0-1	6-34844-00-0-1	9-41504-00-0-1
-	K-17991-00-0-1	9-45866-00-0-1	6-24201-04-0-1	-	-
6-32668-00-0-1	K-17044-00-0-1	9-40443-00-0-1	6-24201-03-0-1	9-43539-00-0-1	9-40873-00-0-1
6-35779-00-L/R-1	K-18048-00-0-1	9-42684-11-0-1	6-24201-03-0-1	-	9-41850-11-0-1

12 mm sopra/sotto				4 mm sopra / 12 mm sotto			
Battuta 18 x 8, 20 x 8		Battuta 24 x 8		Interasse 9 mm		Interasse 13 mm	
-		-		-		-	
sopra	sotto	sopra	sotto	sopra	sotto	sopra	sotto
6-26071-00-0-1	6-24387-00-0-1	6-26071-00-0-1	6-24387-00-0-1	8-00782-00-0-1	8-00781-00-0-1	6-35402-00-L/R-1	6-35401-00-L/R-1
Articolo incontro							
6-26104-06-0-1	6-26104-06-0-1	-	-	-	-	-	-
-	-	-	-	-	-	-	-
6-28062-09-0-1	6-28062-09-0-1	-	-	-	-	-	-
6-28062-89-0-1	6-28062-89-0-1	-	-	-	-	-	-
-	-	6-34153-00-0-1	6-34153-00-0-1	-	-	-	-
-	-	6-34153-02-0-1	6-34153-02-0-1	-	-	-	-
-	-	6-34153-03-0-1	6-34153-03-0-1	-	-	-	-
-	-	-	-	6-25375-00-0-1	6-25376-00-0-1	-	-
-	-	-	-	-	-	6-34153-01-0-1	6-35405-00-0-1
G-17098-00-0-1	G-17098-00-0-1	-	-	-	-	-	-
-	-	6-34153-01-0-1	6-34153-01-0-1	-	-	-	-